

Water / Building & Grounds Report

AUG 2018

Put new oil tank on 2011 plow
Fixed ditch to pinewood tank and removed trees that fell over
Installed new ac unit in pinewood pumphouse
Did lead and copper sampling
Hooked up house on Hornby road
Worked with EE Root and CNG when they were drilling under our line
We helped highway during flooding
Fixed later line that was hit during flooding cleanup
Weed wacked ditch on steel rd by park
Mowed pipelines
Fixed line for trailer park from bank cave and then hit by root